Electrical Safety – Safety Talk



September 2011

Electrocutions are the <u>fifth leading cause of occupational injuries</u>. From 2003 to 2007, there were 1,213 workplace fatalities in the U.S.



The three leading causes of these fatalities were: contact with overhead power lines, contact with wiring and other electrical components, and contact with electrical current from machines/power tools/fixtures.

Remember: you don't have to be an electrician to be exposed to electrical hazards.

Electrical accidents can result in:

- Minor shocks;
- Electrical burns;
- Arc flash explosions;
- Falls from heights;
- Fires: and
- > Electrocutions death!



RESPECT ELECTRICITY!

- Current as little as 60 miliamps at 60 Hz is enough to be fatal.
- > 50 V at 60 Hz can provide enough current to be fatal.
- Never work on live electrical parts!
- Perform lockout/tagout for machines or equipment and unplug power tools prior to servicing.
- Never use conductive ladders or conductive tools around live electricity and power lines.

When using electrically powered machines, equipment, or tools, the following can ensure your safety:

- Guards cover live electrical parts to prevent contact;
- Double insulation or grounding – protect the user against shock in case of internal electrical system failure;
- Fuses shuts off power if too much current is flowing through a circuit; and
- Ground Fault Circuit Interrupters (GFCI) – shuts off power if it senses an imbalance between current to the energized and return conductor.

KEEP IN MIND:

<u>Fuses</u> against <u>fires</u> and property damage, <u>GFCI's</u> protect against electrical <u>shocks</u>.

Always test the GFCI prior to using it!

Here are some basic practices to follow when using electrical tools or machines:

- Ensure the tool, safety devices, and wiring are in good repair <u>prior</u> to using.
- Beware of overloading and interconnecting multiple extension cords and power strips.
- Always use a GFCI when working outside, in wet environments, or around water.
- 4. Never handle a tool by its cord.
- Always use power tools that are grounded (threepronged) or doubleinsulated.
- Remove from service and tag any damaged equipment.

ADDITIONAL INFORMATION:

Review the following policies on the Environmental Health and Safety website:

Hand and Portable Power Tools, Lockout/Tagout, and Machine Guarding